




Flood Hazard Map
Haldimand County
Sandusk Creek



LEGEND

- PARCEL FABRIC
- WATERCOURSE
- CONTOUR (1m)
- CROSS SECTION NUMBER
- REGIONAL STORM FLOOD ELEVATION (m)
- CROSS SECTION LOCATION
- 100-YEAR FLOOD LINE ELEVATION (m)
- REGIONAL STORM FLOOD LINE
- 100-YEAR FLOOD LINE
- SUTTON DAM
- DAM LOCATION AND NAME/ID#
- 02GC026
- STREAM FLOW GAUGE AND REFERENCE ID#
- GBM72U330
- SURVEYED BENCHMARK AND REFERENCE ID#


wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE




HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Flood Hazard Map
Haldimand County
Sandusk Creek



LEGEND

- PARCEL FABRIC
- WATERCOURSE
- CONTOUR (1m)
- CROSS SECTION NUMBER
- REGIONAL STORM FLOOD ELEVATION (m)
- CROSS SECTION LOCATION
- 100-YEAR FLOOD LINE ELEVATION (m)
- REGIONAL STORM FLOOD LINE
- 100-YEAR FLOOD LINE
- SUTTON DAM
- DAM LOCATION AND NAME/ID#
- 02GC026
- STREAM FLOW GAUGE AND REFERENCE ID#
- GBM72U330
- SURVEYED BENCHMARK AND REFERENCE ID#


wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE



HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17


VERTICAL DATUM:
CVGD-2013



Path: I:\LPRCA\FRM-Haldimand.dwg

Plotted By: richard.borbolo
Last Saved By: richard.borbolo
2020-03-30
Last Saved: 2020-03-26

Flood Hazard Map
Haldimand County
Sandusk Creek



LEGEND

- PARCEL FABRIC
- WATERCOURSE
- CONTOUR (1m)
- CROSS SECTION NUMBER
- REGIONAL STORM FLOOD ELEVATION (m)
- CROSS SECTION LOCATION
- 100-YEAR FLOOD LINE ELEVATION (m)
- REGIONAL STORM FLOOD LINE
- 100-YEAR FLOOD LINE
- SUTTON DAM
- DAM LOCATION AND NAME/ID#
- 02GC026
- STREAM FLOW GAUGE AND REFERENCE ID#
- GBM72U330
- SURVEYED BENCHMARK AND REFERENCE ID#


wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE



HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17


VERTICAL DATUM:
CVGD-2013



Path: I:\PRCA\FRM-Haldimand.dwg

Plotted: 2020-03-30
Last Saved: 2020-03-26
Plotted By: richard.borbolo
Last Saved By: richard.borbolo

Flood Hazard Map
Haldimand County
Sandusk Creek



- LEGEND
- PARCEL FABRIC
 - WATERCOURSE
 - CONTOUR (1m)
 - CROSS SECTION NUMBER
 - REGIONAL STORM FLOOD ELEVATION (m)
 - CROSS SECTION LOCATION
 - 100-YEAR FLOOD LINE ELEVATION (m)
 - REGIONAL STORM FLOOD LINE
 - 100-YEAR FLOOD LINE
 - SUTTON DAM
 - DAM LOCATION AND NAME/ID#
 - 02GC026
 - STREAM FLOW GAUGE AND REFERENCE ID#
 - GBM72U330
 - SURVEYED BENCHMARK AND REFERENCE ID#

wood.


Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.



REVISIONS


No.	Description	BY	DATE

Sheet 5 of 11




HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013




Aerial photography from Southwestern Ontario Orthophotography Project 2015 (Spring 2015)
DTM/Contours generated from Lake Erie LIDAR (LIO Dataset, by MNR), Spring 2016 through Spring 2018



Path: I:\PRCA\FRM-Haldimand.dwg

Plotted By: richard.bortolo
Last Saved By: richard.bortolo
2020-03-30
2020-03-26

Flood Hazard Map
Haldimand County
Sandusk Creek



- LEGEND
- PARCEL FABRIC
 - WATERCOURSE
 - CONTOUR (1m)
 - CROSS SECTION NUMBER
 - REGIONAL STORM FLOOD ELEVATION (m)
 - CROSS SECTION LOCATION
 - 100-YEAR FLOOD LINE ELEVATION (m)
 - REGIONAL STORM FLOOD LINE
 - 100-YEAR FLOOD LINE
 - SUTTON DAM
 - DAM LOCATION AND NAME/ID#
 - 02GC026
 - STREAM FLOW GAUGE AND REFERENCE ID#
 - GBM72U330
 - SURVEYED BENCHMARK AND REFERENCE ID#

wood.


Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.



REVISIONS



No.	Description	BY	DATE

Sheet 6 of 11





HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Flood Hazard Map
Haldimand County
Sandusk Creek



wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE





HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Flood Hazard Map
Haldimand County
Sandusk Creek




wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE




HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Flood Hazard Map
Haldimand County
Sandusk Creek



- LEGEND
- PARCEL FABRIC
 - WATERCOURSE
 - CONTOUR (1m)
 - CROSS SECTION NUMBER
 - REGIONAL STORM FLOOD ELEVATION (m)
 - CROSS SECTION LOCATION
 - 100-YEAR FLOOD LINE ELEVATION (m)
 - REGIONAL STORM FLOOD LINE
 - 100-YEAR FLOOD LINE
 - SUTTON DAM
 - DAM LOCATION AND NAME/ID#
 - 02GC026
 - STREAM FLOW GAUGE AND REFERENCE ID#
 - GBM72U330
 - SURVEYED BENCHMARK AND REFERENCE ID#


wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE



HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013




Path: I:\PRCA\FRM-Haldimand.dwg

Plotted By: richard.borbolo
Last Saved By: richard.borbolo

2020-03-30
2020-03-26

Flood Hazard Map
Haldimand County
Sandusk Creek



- LEGEND
- PARCEL FABRIC
 - WATERCOURSE
 - CONTOUR (1m)
 - CROSS SECTION NUMBER
 - REGIONAL STORM FLOOD ELEVATION (m)
 - CROSS SECTION LOCATION
 - 100-YEAR FLOOD LINE ELEVATION (m)
 - REGIONAL STORM FLOOD LINE
 - 100-YEAR FLOOD LINE
 - SUTTON DAM
 - DAM LOCATION AND NAME/ID#
 - 02GC026
 - STREAM FLOW GAUGE AND REFERENCE ID#
 - GBM72U330
 - SURVEYED BENCHMARK AND REFERENCE ID#


wood.

Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.





REVISIONS

No.	Description	BY	DATE



HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Path: I:\PRCA\FRM-Haldimand.dwg

Plotted By: richard.borbolo
Last Saved By: richard.borbolo


2020-03-30
2020-03-26



Long Point Region
Conservation Authority

Flood Hazard Map
Haldimand County
Sandusk Creek

INDEX MAP



LEGEND

- PARCEL FABRIC
- WATERCOURSE
- CONTOUR (1m)
- CROSS SECTION NUMBER
- REGIONAL STORM FLOOD ELEVATION (m)
- CROSS SECTION LOCATION
- 100-YEAR FLOOD LINE ELEVATION (m)
- REGIONAL STORM FLOOD LINE
- 100-YEAR FLOOD LINE
- SUTTON DAM
- DAM LOCATION AND NAME/ID#
- 02GC026
- STREAM FLOW GAUGE AND REFERENCE ID#
- GBM72U330
- SURVEYED BENCHMARK AND REFERENCE ID#

wood.


Please note that the Professional Engineer's stamp verifies the flood line and associated data, not the map unless otherwise noted.



REVISIONS



No.	Description	BY	DATE

Sheet 11 of 11



HORIZONTAL PROJECTION:
UTM NAD83 ZONE 17

VERTICAL DATUM:
CVGD-2013



Plotted: 2020-03-30
Last Saved: 2020-03-26
Plotted By: richard.borbolo
Last Saved By: richard.borbolo
Path: I:\PRCA\FRM-Haldimand.dwg